


SKIL MODEL 511 JIG SAW



PART NO.	PART NAME	NO. USED	REMARKS	PART NO.	PART NAME	NO. USED	REMARKS
24	Lockwasher	9	For 660, 3712 & 3713	11028	Set Screw	2	For 11029
63	Terminal	3	Cord & Field Leads	11029	Collar	1	Holds Blade
660	Screw	1	Ground	11030	Foot	1	
738	Set Screw	2	For 6837	11032	Cord & Plug	1	150-250V
1170	Brush Cap	2		11033	Roller	1	For 11018
2518	Chapman Plug	2	For 11023	11038	Armature	1	115V
3712	Screw	4	For 11023 & 11027	11044	Field	1	115V
3713	Screw	4	For 11023 & 11044	11165	Roller	2	For 11016
6837	Brush Holder	2		13321	Strain Relief	1	
6839	Insulating Washer	2	For 6837	13570	Ball Bearing	1	Fan End 11038
11004	Fan	1		13747	Screw	1	Holds 11008 to 11006
11006	Drive Shaft	1		13916	Roller Follower	1	
11007	Balance Weight	2		13917	Plate	1	Bet. 11027 & 13916
11008	Yoke	1	For 11006	16167	Connector	1	Field Lead
11010	Plug	1	For 11006	16336	Washer	2	For 3712
11011	Gear	2	For 11006 & 11007	16432	Felt Washer	1	For 16481
11018	Gear & Shaft Ass'y	1	Drives 11008	16474	Screw	1	For 11030
	11013 Dowel Pin	1	Large	16475	Screw	3	For 11030
	11015 Dowel Pin	1	Small	16481	Cap	1	For 11023
11019	Switch	1		17502	Screw	1	Holds 11008 to 11006
11020	Baffle Plate	1		17552	Washer	1	Bet. 11018 & 11027
11023	Front Housing Ass'y	1		18041	Brush & Spring	2	
	11016 Shaft	2					
11024	Retaining Ring	2	Retains 11165				
11025	Rear Housing Ass'y	1					
	1304 Bronze Brg.	1					
	2525 Felt Disc	1					
11026	Cord & Plug	1	115V				
11027	Bearing Plate Ass'y	1					
	17149 Bronze Brg.	1					

MOTOR DATA

NAMEPLATE VOLTS	ARMATURE NUMBER	FIELD NUMBER
115	11038	11044
150	11040	11046
220-230	11042	11048
240-250	11043	11049

